HISTORIC AMERICAN BUILDINGS SURVEY

Index to Photographs

Leesburg Townsite, Cabin (Feature 14)
Napias Creek
Salmon Vicinity
Lemhi County
Idaho

HABS No. ID-106-K

NOTE: Photographs were taken Lon Johnson, photographer, June 1992

ID-106-K-1	VIEW SHOWING SOUTH FRONT AND EAST SIDE OF CABIN (Feature 14), LOOKING NORTH-NORTHWEST
ID-106-K-2	VIEW SHOWING WEST SIDE OF CABIN (Feature 14), LOOKING SOUTHEAST
ID-106-K-3	DETAIL VIEW OF LOG CONSTRUCTION AND WINDOW FRAME OF CABIN (Feature 14), LOOKING NORTH
ID-106-K-4	DETAIL VIEW OF CHINESE CHARACTERS AND INTERIOR LOG CONSTRUCTION OF CABIN (Feature 14), LOOKING SOUTH